

Посібник користувача - Енергоефективність / Vadovas - Energijos vartojimo efektyvumo / Manwal ghall-Utent - Effiċjenza fl-Energija / Kézi - Energiahatékonyaság / Příručka - Energetická účinnost / Рігучка - Energetická účinnost' / Manual - Eficientă Energetică / Ręczny - Efektywność energetyczna / Priručnik - Energetska efikasnost / Navodilo - Energetska učinkovitost / Εγχειρίδιο - Ενεργειακή Αποδοτικότητα / Manuel - Energi Verimliliği / Наръчник - Енергийна ефективност / Упутство - Енергетска ефикасност / Lámhleabhar Úsáideoir - Éifeachtúlacht Fuinnimh

	PF	UA	LT	MT	HU	CZ	SK	RO	PL	HR	SL	GR	TR	BG	SR	GA
S	FRANKE															
M	330.0528.067															
AEChood	55,8															
EChood	A															
FDEhood	29,2															
FDEC	A															
LEhood	68															
LEC	A															
GFEhood	75,1															
GFEC	C															
Qmin	280															
Qmax	560															
Qboost	700															
Qboost	52															
SPEmin	65															
SPEmax	69															
SPEboost																
PO	0,49															
Ps	N/A															
PI																
F	0,9															
EElhood	52,0															
Qbep	390,0															
Pbep	444															
Qmax	700,0															
Wbep	165,0															
WL	2,2															
Emiddle	150															
Lwa	65															
WL																
Emiddle																
Lwa																
PO																
Ps																
PI																
F																
EElhood																
Qbep																
Pbep																
Qmax																
Wbep																
WL																
Emiddle																
Lwa																
WL																
Emiddle																
Lwa																
PO																
Ps																
PI																
F																
EElhood																
Qbep																
Pbep																
Qmax																
Wbep																
WL																
Emiddle																
Lwa																
WL																
Emiddle																
Lwa																
PO																
Ps																
PI																
F																
EElhood																
Qbep																
Pbep																
Qmax																
Wbep																
WL																
Emiddle																
Lwa																
WL																
Emiddle																
Lwa																
PO																
Ps																
PI																
F																
EElhood																
Qbep																
Pbep																
Qmax																
Wbep																
WL																
Emiddle																
Lwa																
WL																
Emiddle																
Lwa																
PO																
Ps																
PI																
F																
EElhood																
Qbep																
Pbep																
Qmax																
Wbep																
WL																
Emiddle																
Lwa																
WL																
Emiddle																
Lwa																
PO																
Ps																
PI																
F																
EElhood																
Qbep																
Pbep																
Qmax																
Wbep																
WL																
Emiddle																
Lwa																
WL																
Emiddle																